




$n_d - \nu_d$ Diagram **GMO**



Hk-Fa (Knoop Hardness-Abrasion Factor)Diagram



$n_e - \nu_e$ Diagram



$P_{g,F} / \nu_d$ Diagram

